

Most instruments were in perfect working condition during the audit. Improvements following the audit include:

- installing a dryer on the aethalometer sampling line
- correct data submission protocol for number size distribution measurements
- repairing the multi angle absorption photometer filter holder