

The laboratory book has been installed after the audit in addition to the electronic logbook file.
The sheath air drier has been installed into the SMPS system.
The absolute pressure sensor has been installed in the SMPS system.